+ AUTODOC CLUB

How to change pollen filter on VW Amarok
Pickup (2HA, 2HB, S1B, S6B, S7A, S7B) –
replacement guide







SIMILAR VIDEO TUTORIAL



This video shows the replacement procedure of a similar car part on another vehicle

i Important!

This replacement procedure can be used for:

VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B) 2.0 TSI, VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B) 2.0 BiTDI 4motion, VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B) 2.0 BiTDI, VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B) 2.0 TDI 4motion, VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B) 2.0 TDI, VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B) 3.0 TDI 4motion, VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B) 3.0 TDI

The steps may slightly vary depending on the car design.

This tutorial was created based on the replacement procedure for a similar car part on: VW Transporter V Van (7HA, 7HH, 7EA, 7EH) 1.9 TDI


CLUB.AUTODOC.CO.UK 1–7







REPLACEMENT: POLLEN FILTER – VW AMAROK PICKUP (2HA, 2HB, S1B, S6B, S7A, S7B). TOOLS YOU MIGHT NEED:



- Drive socket # 5,5
- Torx bit T20

Ratchet wrench

Buy tools

CLUB.AUTODOC.CO.UK 2-7







Replacement: pollen filter – VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B). AUTODOC recommends:

- Replace the cabin filter at least once every six months, in early spring and autumn seasons.
- Follow the terms, recommendations and requirements of the part operation provided by the manufacturer.
- If the air flow into the cabin has sharply reduced, replace the filter before a scheduled maintenance.
- All work should be done with the engine stopped.

CARRY OUT REPLACEMENT IN THE FOLLOWING ORDER:

1 Move the passenger seat fully backwards.

3

Unscrew the fasteners of the passenger side kick panel. Use Torx T20.



Remove the protective cover under the glove box.



CLUB.AUTODOC.CO.UK 3-7







Unscrew the fasteners of the cabin filter housing cover. Use a drive socket #5,5. Use a ratchet wrench.



Remove the cabin filter housing cover.



Remove the cabin filter.



Replacement: pollen filter – VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B). AUTODOC experts recommend:

• Do not attempt to clean and reuse the filter - it will affect the quality of air cleaning inside the car.

CLUB.AUTODOC.CO.UK 4–7







Install the cabin filter to its mounting seat.



Replacement: pollen filter – VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B). AUTODOC recommends:

- Follow the air flow direction arrow on the filter.
- Check out the correct location of the filter element. Do not skew.
- Attention! Use quality components. VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B)

Reinstall the cabin filter housing cover.

9



Screw in the fasteners of the cabin filter housing cover. Use a drive socket #5,5. Use a ratchet wrench.



CLUB.AUTODOC.CO.UK 5–7








10 Install and secure the protective cover under the glove box.



Screw in the fasteners of the passenger side kick panel. Use Torx T20.



AUTODOC recommends:

- Replacement: pollen filter VW Amarok Pickup (2HA, 2HB, S1B, S6B, S7A, S7B).
 Do not use excessive force during installation. This may damage the fasteners.
- Return the passenger seat to its initial position.
- Switch on the ignition.
- Switch on the air conditioning system. This is necessary in order to make sure that the component operates properly.
- Switch off the ignition.




VIEW MORE TUTORIALS

CLUB.AUTODOC.CO.UK 6-7





AUTODOC — TOP QUALITY AND AFFORDABLE CAR PARTS ONLINE



A GREAT SELECTION OF SPARE PARTS FOR YOUR CAR

POLLEN FILTER: A WIDE SELECTION

① DISCLAIMER:

The document contains only general recommendations that may be useful for you when you perform repair or replacement work. AUTODOC shall not be liable for any loss, injury, damage of property occurring in the repair or replacement process due to incorrect use or misinterpretation of the provided information.

AUTODOC shall not be liable for any possible mistakes and uncertainties in this guide. The information provided is for information purposes only and cannot replace advice from specialists.

AUTODOC shall not be liable for incorrect or hazardous usage of equipment, tools and car parts. AUTODOC strongly recommends to be careful and observe the safety rules when performing repair or replacement works. Remember: usage of low quality auto parts does not guarantee you the appropriate level of road safety.

© Copyright 2023 – All the contents of this website, in particular texts, photographs and graphics, are protected by copyright. All rights, including reproduction, publication, editing and translation rights, are reserved by AUTODOC SE.

CLUB.AUTODOC.CO.UK 7-7