

How to change pollen filter on VW Golf VI Hatchback (5K1) – replacement guide





## SIMILAR VIDEO TUTORIAL



This video shows the replacement procedure of a similar car part on another vehicle

## i Important!

This replacement procedure can be used for:

VW Golf VI Hatchback (5K1) 1.6 MultiFuel, VW Golf VI Hatchback (5K1) 2.0 R 4motion, VW Golf VI Hatchback (5K1) 1.2 TSI, VW Golf VI Hatchback (5K1) 2.0 GTi, VW Golf VI Hatchback (5K1) 1.4, VW Golf VI Hatchback (5K1) 1.6, VW Golf VI Hatchback (5K1) 1.4 TSI, VW Golf VI Hatchback (5K1) 2.0 TDI, VW Golf VI Hatchback (5K1) 1.6 BiFuel, VW Golf VI Hatchback (5K1) 1.6 TDI, VW Golf VI Hatchback (5K1) 2.0 TDI 4motion, VW Golf VI Hatchback (5K1) 1.8 TSI

The steps may slightly vary depending on the car design.

This tutorial was created based on the replacement procedure for a similar car part on: VW Passat B7 Saloon (362) 2.0 TDI

CLUB.AUTODOC.CO.UK 1–7





# Replacement: pollen filter – VW Golf VI Hatchback (5K1). AUTODOC experts recommend:

- Replace the cabin filter at least once every six months, in early spring and autumn seasons.
- Follow the terms, recommendations and requirements of the part operation provided by the manufacturer.
- If the air flow into the cabin has sharply reduced, replace the filter before a scheduled maintenance.
- Please note: all work on the car VW Golf VI Hatchback (5K1) should be done
  with the engine switched off.

#### CARRY OUT REPLACEMENT IN THE FOLLOWING ORDER:

- Move the passenger seat fully backwards.
- Unscrew the fasteners of the bottom trim panel.



Remove the bottom cover of the glove box.

3



CLUB.AUTODOC.CO.UK 2-6









Remove the cabin filter housing cover.



Remove the cabin filter.



Replacement: pollen filter – VW Golf VI Hatchback (5K1). Tip from AUTODOC experts:

- Do not attempt to clean and reuse the filter it will affect the quality of air cleaning inside the car.
- 6 Install the cabin filter to its mounting seat.



CLUB.AUTODOC.CO.UK 3-6





# Replacement: pollen filter – VW Golf VI Hatchback (5K1). AUTODOC experts recommend:

- Follow the air flow direction arrow on the filter.
- Check out the correct location of the filter element. Do not skew.
- Attention! Use quality filters VW Golf VI Hatchback (5K1).
- Reinstall the cabin filter housing cover. Position the part using the guides and lock the fasteners.



8 Install the bottom cover of the glove box.

9



Screw in the fasteners of the bottom trim panel.



CLUB.AUTODOC.CO.UK 4-6



10





Return the passenger seat to its initial position.

- Switch on the ignition.
- Switch on the air conditioning system. This is necessary in order to make sure that the component operates properly.



Switch off the ignition.



**VIEW MORE TUTORIALS** 

CLUB.AUTODOC.CO.UK 5-6





# AUTODOC — TOP QUALITY AND AFFORDABLE CAR PARTS ONLINE



A GREAT SELECTION OF SPARE PARTS FOR YOUR CAR

**POLLEN FILTER: A WIDE SELECTION** 

## **① DISCLAIMER:**

The document contains only general recommendations that may be useful for you when you perform repair or replacement work. AUTODOC shall not be liable for any loss, injury, damage of property occurring in the repair or replacement process due to incorrect use or misinterpretation of the provided information.

AUTODOC shall not be liable for any possible mistakes and uncertainties in this guide. The information provided is for information purposes only and cannot replace advice from specialists.

AUTODOC shall not be liable for incorrect or hazardous usage of equipment, tools and car parts. AUTODOC strongly recommends to be careful and observe the safety rules when performing repair or replacement works. Remember: usage of low quality auto parts does not guarantee you the appropriate level of road safety.

© Copyright 2021 – All the contents of this website, in particular texts, photographs and graphics, are protected by copyright. All rights, including reproduction, publication, editing and translation rights, are reserved by AUTODOC GmbH.

CLUB.AUTODOC.CO.UK 6-6