+ AUTODOC CLUB

How to change pollen filter on CITROËN C4 II
Box Body / Hatchback
(NC_) – replacement guide







SIMILAR VIDEO TUTORIAL



This video shows the replacement procedure of a similar car part on another vehicle

i Important!

This replacement procedure can be used for: CITROËN C4 II Box Body / Hatchback (NC_) 1.6 BlueHDi, CITROËN C4 II Box Body / Hatchback (NC_) 1.6 HDi

The steps may slightly vary depending on the car design.

This tutorial was created based on the replacement procedure for a similar car part on: CITROËN C3 I Hatchback (FC_, FN_) 1.4 i

CLUB.AUTODOC.CO.UK 1–7







REPLACEMENT: POLLEN FILTER – CITROËN C4 II BOX BODY / HATCHBACK (NC_). TOOLS YOU NEED:



Phillips screwdriver

Fender cover

Buy tools

CLUB.AUTODOC.CO.UK 2-7







Replacement: pollen filter – CITROËN C4 II Box Body / Hatchback (NC_). AUTODOC experts recommend:

- Replace the cabin filter at least once every six months, in early spring and autumn seasons.
- Follow the terms, recommendations and requirements of the part operation provided by the manufacturer.
- If the air flow into the cabin has sharply reduced, replace the filter before a scheduled maintenance.
- Warning! Shut down the engine before starting any work CITROËN C4 II Box Body / Hatchback (NC_).

CARRY OUT REPLACEMENT IN THE FOLLOWING ORDER:

- Open the bonnet.
- Use a fender protection cover to prevent damaging paintwork and plastic parts of the car.
- Unscrew the fasteners of the cabin filter housing cover. Use a Phillips screwdriver.



Remove the cabin filter housing cover.



CLUB.AUTODOC.CO.UK 3-7







Replacement: pollen filter – CITROËN C4 II Box Body / Hatchback (NC_). Professionals recommend:

 Do not apply excessive force when removing the part. Otherwise you may damage it.

5

Remove the cabin filter.



Replacement: pollen filter – CITROËN C4 II Box Body / Hatchback (NC_). Tip:

• Do not attempt to clean and reuse the filter - it will affect the quality of air cleaning inside the car.

6

Install the cabin filter to its mounting seat.



CLUB.AUTODOC.CO.UK 4–7







Replacement: pollen filter – CITROËN C4 II Box Body / Hatchback (NC_). Tip from AUTODOC experts:

- Check out the correct location of the filter element. Do not skew.
- Follow the air flow direction arrow on the filter.
- Attention! Use quality filters CITROËN C4 II Box Body / Hatchback (NC_).
- Reinstall the cabin filter housing cover.



Screw in the fasteners of the cabin filter housing cover. Use a Phillips screwdriver.



- 9 Switch on the ignition.
- Switch on the air conditioning system. This is necessary in order to make sure that the component operates properly.
- Switch off the ignition.
- Remove the fender protection cover.

CLUB.AUTODOC.CO.UK 5–7







13

Close the hood.




VIEW MORE TUTORIALS

CLUB.AUTODOC.CO.UK 6-7





AUTODOC — TOP QUALITY AND AFFORDABLE CAR PARTS ONLINE



A GREAT SELECTION OF SPARE PARTS FOR YOUR CAR

POLLEN FILTER: A WIDE SELECTION

① DISCLAIMER:

The document contains only general recommendations that may be useful for you when you perform repair or replacement work. AUTODOC shall not be liable for any loss, injury, damage of property occurring in the repair or replacement process due to incorrect use or misinterpretation of the provided information.

AUTODOC shall not be liable for any possible mistakes and uncertainties in this guide. The information provided is for information purposes only and cannot replace advice from specialists.

AUTODOC shall not be liable for incorrect or hazardous usage of equipment, tools and car parts. AUTODOC strongly recommends to be careful and observe the safety rules when performing repair or replacement works. Remember: usage of low quality auto parts does not guarantee you the appropriate level of road safety.

© Copyright 2023 – All the contents of this website, in particular texts, photographs and graphics, are protected by copyright. All rights, including reproduction, publication, editing and translation rights, are reserved by AUTODOC SE.

CLUB.AUTODOC.CO.UK 7-7