How to change auxiliary indicator on RENAULT 19 II Convertible – replacement guide



This video shows the replacement procedure of a similar car part on another vehicle


Important!

This replacement procedure can be used for: RENAULT 19 II Convertible 1.7, RENAULT 19 II Convertible 1.8 16V, RENAULT 19 II Convertible 1.8 (D53Y) (F3P 704, F3P 705, F3P 706, F3P 707, F3P 708, F3P 760), RENAULT 19 II Convertible 1.8, RENAULT 19 II Convertible 1.8 (D53Y)

The steps may slightly vary depending on the car design.

This tutorial was created based on the replacement procedure for a similar car part on: RENAULT MASTER II Box (FD) 2.2 dCl 90

club.autodoc.co.uk 1-5



Plastic trim removal tool

Replacement: auxiliary indicator - RENAULT 19 II Convertible. AUTODOC recommends:

The procedure for replacing the right and left side indicators is identical.
All the work should be carried out with the ignition switched off.

Replacement: auxiliary indicator – RENAULT 19 II Convertible. Recommended sequence of steps:



2 Detach the bulb holder from the side indicator light.



3 Attach the bulb holder to a new side indicator light.



club.autodoc.co.uk 3-5

4 Install the new side indicator ligh



5 Check that the new component is working. Well done! View more tutorials club autodoc.co.uk 4-5

AUTODOC — top quality and affordable car parts online AUTODOC mobile app: Great deals and convenient shopping



A great selection of spare parts for your car Auxiliary indicator: a wide selection Disclaimer:

The document contains only general recommendations that may be useful for you when you perform repair or replacement work. AUTODOC shall not be liable for any loss, injury, damage of property occurring in the repair or replacement process due to incorrect use or misinterpretation of the provided information.

AUTODOC shall not be liable for any possible mistakes and uncertainties in this guide. The information provided is for information purposes only and cannot replace advice from specialists.

AUTODOC shall not be liable for incorrect or hazardous usage of equipment, tools and car parts. AUTODOC strongly recommends to be careful and observe the safety rules when performing repair or replacement works. Remember: usage of low quality auto parts does not guarantee you the appropriate level of road safety.

© Copyright 2025 – All the contents of this website, in particular texts, photographs and graphics, are protected by copyright. All rights, including reproduction, publication, editing and translation rights, are reserved by AUTODOC SE.

club.autodoc.co.uk